OPERATING INSTRUCTIONS







INSTALLATION


1. Strip back the cable jacket and insulation to the length indicated in the following table.

Pulling Eye	Strip Length
24300-001	2"
24300-004	2-3/8"
24300-350	2-3/4"
24300-500	2-3/4"





- 2. Insert the cable into the pulling eye.
- 3. Tighten the three set screws which secure the cable.



4. Repeat for the other cables.

SAFETY



- 1. Never use a worn, defective or incomplete component. Ensure that all components of the pulling system are able to withstand the maximum pulling loads. Components not rated for the pull force may break and release the stored energy of the pull.
- 2. Any attempt to modify the Multiplex Pulling Eye will void the warranty and may result in property damage, severe bodily harm, or death.
- 3. Be prepared for the unexpected. Use recognized safety practices and wear recognized safety equipment.

SERVICE



1. After each use, assess the condition of the Multiplex Pulling Eye checking for wear and external damage.

1 OF 1 7/19/2011